

Using the Studio VectorScope

Have these on: EX Ref, DC REST, O/P, H

A shows Program Bus

Flat Chroma and Luminance

Chr Chroma

LP Luminance

You can display all of these signal references at once:

Be in O-P mode - Go Flat; then LP; then Chr